




# 1988 Hawker 800A

L&L International Ltd.  
5952 NE 4<sup>th</sup> Ave Miami, FL  
P. +1 (305) 754-3313  
E. Sales@L-Lint.com

**MSN: 258104**

**Registration: N211JN**





# 1988 Hawker 800A

L&L International Ltd.  
5952 NE 4<sup>th</sup> Ave Miami, FL  
P. +1 (305) 754-3313  
E. Sales@L-Lint.com

## Airframe

Total Time 12,035 Hours  
Total Landings 7,889 Landings  
No Known Damage History  
(2) USA Owners Since New

## Programs

Engines: Enrolled on MSP Gold  
FlightDocs Maintenance Tracking System

## Engines

Honeywell TFE731-5R-1H	Left	Right
Serial Number	P91318	P91321
Hours	12,035	12,035
Cycles	7,889	7,889

## APU

Sundstrand T-62T-40C8D1	
Serial Number	887619
Hours	7,148.5
Cycles	10,049





# 1988 Hawker 800A

L&L International Ltd.  
5952 NE 4<sup>th</sup> Ave Miami, FL  
P. +1 (305) 754-3313  
E. Sales@L-Lint.com

## Avionics


- Autopilot: Collins APS 85
- SATCOM: Iridium Global Sat Phone
- Nav Radios: Dual Collins VIR-32
- Flight Director: Collins FCS-850
- FMS: Dual Universal FMS UNS 1-D
- RMI: Dual Collins SDU-640A
- TAWS: Allied Signal Mark VII EGPWS
- CVR: Fairchild
- ADF: Collins ADS-60 w CTL
- TCAS: Collins w/ MFD 85C Display
- DME: Dual Collins DME-42
- Radar Altimeter: Collins TWR-850 w/ Turbulence
- Weather Radar: TWR-850 w/ Turbulence Detection
- Altimeter: Dual ALT-850B
- Comm: Dual Collins VHF-422C
- Transponder: Dual Enhanced Mode S
- Flight Data Recorder

## Additional Equipment

- Thrust Reversers
- New Brakes, Wheels, and Tires (2016)
- New A Panels (2016)
- CVR
- ELT Satellite 406 Htz
- Lead Acid Battery
- Flight Rules IFR
- Dual Collins HF Transceiver
- Dual Collin EFIS-86E
- RVSM
- Tel-Tail Flood Light System

## Maintenance Status

- Completed Logbooks
- Always Hangared
- MSP Gold Inspections c/w 11/2016 @ Duncan Aviation
- 800 Hour B1-12 & E Check Completed 11/ 2016
- SOH: 8,454.1 c/w by Premier Turbines 2004
- SHI: 10,554.7 c/w by Dallas Airmotive 2008
- **E,F,G Inspections and X-Rays in Progress Sept 2017 by Stevens Aviation**



# 1988 Hawker 800A

L&L International Ltd.  
5952 NE 4<sup>th</sup> Ave Miami, FL  
P. +1 (305) 754-3313  
E. Sales@L-Lint.com

## Exterior

- Paint touch up in 2013
- Two-Toned, White Upper with Blue Base, and Gray and Midnight Blue Accent Stripes

## Interior

Executive 10 Passenger Interior Partially Refurbished in 2013

### Layout

- (3) Passenger Divan Opposite (1) Club Seat with Fold Out Table
- (4) Place Club Arrangement with Two Fold Out Tables

### Finishes:

Garrett Leather Berkshire 848 Seating  
Cabinetry Light Champagne Birds-Eye Wood & Tables w/ Almond Tops  
Sand Ultra suede headliner  
Scott Group 100% Wool Carpeting

Fwd Refreshment Center w/ Large Galley Workscope and Microwave Oven

Entertainment Equipment: DVD/CD Player, Sony CD Player, and Heat & Air Conditioning Controls

- (1) Jump Seat
- (1) Aft Belted Lavatory




*Specifications are Subject to Verification. Aircraft is Subject to Prior Sale, Lease, and/or Removal from the Market Without Prior Notice.*



# 1988 Hawker 800A

L&L International Ltd.  
5952 NE 4<sup>th</sup> Ave Miami, FL  
P. +1 (305) 754-3313  
E. Sales@L-Lint.com





# 1988 Hawker 800A

L&L International Ltd.  
5952 NE 4<sup>th</sup> Ave Miami, FL  
P. +1 (305) 754-3313  
E. Sales@L-Lint.com

